

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

U.S. INSPECTION STATION, MAIN BUILDING
(U.S. Border Station)
California State Highway 188, Tecate Road
Tecate
San Diego County
California

HABS No. CA-2782-A

8 x 10 enlargements from 4 x 5 negatives

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Edward Gohlich, photographer

- | | |
|-------------|--|
| CA-2782-A-1 | U.S. INSPECTION STATION, TECATE, EXTERIOR VIEW,
LOOKING NORTHEAST, JUNE 2003 |
| CA-2782-A-2 | U.S. INSPECTION STATION, TECATE, EXTERIOR VIEW,
LOOKING SOUTHEAST, JUNE 2003 |
| CA-2782-A-3 | U.S. INSPECTION STATION, TECATE, EXTERIOR VIEW, NORTH
FACADE. SEPTEMBER 22, 2003. |
| CA-2782-A-4 | U.S. INSPECTION STATION, TECATE, EXTERIOR VIEW,
LOOKING SOUTHWEST. JUNE 10, 2003. |
| CA-2782-A-5 | U.S. INSPECTION STATION, TECATE, EXTERIOR VIEW,
LOOKING WEST. SEPTEMBER 22, 2003. |
| CA-2782-A-6 | U.S. INSPECTION STATION, TECATE, EXTERIOR VIEW,
LOOKING SOUTH. SEPTEMBER 22, 2003. |
| CA-2782-A-7 | U.S. INSPECTION STATION, TECATE, EXTERIOR VIEW,
LOOKING WEST TOWARD TWO-STORY PORTION. SEPTEMBER
22, 2003. |
| CA-2782-A-8 | U.S. INSPECTION STATION, TECATE, EXTERIOR VIEW,
LOOKING NORTHWEST FROM SOUTH ROOF. SEPTEMBER 22,
2003. |

U.S. INSPECTION STATION, MAIN BUILDING
HABS No. CA 2782-A
INDEX TO PHOTOGRAPHS
(Page 2)


CA-2782-A-9	U.S. INSPECTION STATION, TECATE, EXTERIOR VIEW, LOOKING NORTHWEST. JUNE 10, 2003.
CA-2782-A-10	U.S. INSPECTION STATION, TECATE, EXTERIOR VIEW, SOUTH FACADE. SEPTEMBER 22, 2003.
CA-2782-A-11	U.S. INSPECTION STATION, TECATE, EXTERIOR VIEW, PARAPET AND SHIELD DETAIL ON WEST FACADE, LOOKING EAST. SEPTEMBER 22, 2003.
CA-2782-A-12	U.S. INSPECTION STATION, TECATE, EXTERIOR VIEW, WINDOW DETAIL ON WEST FACADE, LOOKING EAST. SEPTEMBER 22, 2003.
CA-2782-A-13	U.S. INSPECTION STATION, TECATE, EXTERIOR VIEW, MAIN ENTRY DETAIL ON WEST FACADE, LOOKING EAST. SEPTEMBER 22, 2003.
CA-2782-A-14	U.S. INSPECTION STATION, TECATE, INTERIOR OF LOBBY, LOOKING NORTHEAST. JUNE 10, 2003.
CA-2782-A-15	U.S. INSPECTION STATION, TECATE, INTERIOR OF FRONT DESK AREA, LOOKING SOUTHEAST. JUNE 10, 2003.
CA-2782-A-16	U.S. INSPECTION STATION, TECATE, INTERIOR OF SOUTH

U.S. INSPECTION STATION, MAIN BUILDING


HABS No. CA 2782-A

INDEX TO PHOTOGRAPHS

(Page 3)



U.S. INSPECTION STATION, MAIN BUILDING
HABS No. CA 2782-A
INDEX TO PHOTOGRAPHS
(Page 4)



DRAWN BY: MIKE BOETZ & RAHEL KINI, ARCHITECT MILFORD WAYNE DONALDSON, FAIA (2003)

NAME AND ADDRESS OF STRUCTURE

U.S. INSPECTION STATION, TECATE

TECATE, SAN DIEGO COUNTY, CALIFORNIA

SHEET 2 OF 2

HISTORIC AMERICAN
BUILDINGS SURVEY
CA - 2782 - A

LEGEND OF CONCRETE
BLOCK NUMBER